SWAVESEY Summary of SHLAA and SA Assessments

Settlement Category: Group Village

SHLAA Site Reference	Site 008	Site 048	Site 049	Site 050	Site 065	Site 071	Site 083	Site 169	Site 250	Site 287
Address (summary)	adjacent to	The Farm, Boxworth End	Boxworth	Dairy Farm, 31 Boxworth End	Land abutting Fen Drayton Road	Hale Road	Land south of Whitton Close and west of Boxworth End	Market Street	Driftwood Farm	Land adjacent Fen Drayton Road
Site Size (gross ha)	0.26	1.88	61.54	3.55	7.22	10.76	7.65	1.09	1.74	1.30
Notional dwelling capacity	3	38	738	80	162	81	75	0	47	26
SHLAA strategic considerations	0	0	-	0	0		0			-
Green belt	0	0	0	0	0	0	0	0	0	0
SHLAA significant local considerations					0		0			-
Landscape and Townscape impact							-			
SHLAA site specific factors							0			
Accessibility to key local services and facilities (SA criteria 37)	-	-	-	-	-	-	-	-	-	-
Distance to key local services and facilities (SA criteria 38)	-				0	+		+++	+++	0
Accessibility to a range of employment opportunities (SA criteria 48)	+	+	+	+	+	+	+	+	+	+
Accessibility by sustainable transport modes such as walking, cycling and public transport (SA criteria 51)	+	+	0	+	0	+	+	+	+	0
Sustainable Development Potential										

Site Comments:

Site 008	East of Middlewatch. Significant heritage, townscape and landscape impacts - adjacent to several LB. Possible noise from adjacent business centre. Unsuitable highway access. Utility & services require upgrade.
Site 048	East of Boxworth End. Significant heritage, townscape and landscape impacts - LB within site & ICF along road frontage. Utility & services require upgrade.
	Very large site to east of Boxworth End. Significant heritage, townscape and landscape impacts - LB within site & ICF along road frontage. Scale out of proportion to village and character of linear / rural. North eastern part within Flood Zones 2 & 3. Air quality & noise issues from scale of development, and noise and malodour from farm. A14 capacity issues. Utility & services require significant upgrade.
Site 050	East of Boxworth End. Significant heritage, townscape and landscape impacts - LB within site & ICF along road frontage. Utility & services require upgrade.
Site 065	Site adjacent to Secondary School on west. Adverse townscape and landscape impacts - exposed site. A14 capacity issues. Utility & services require upgrade.
Site 071	Large site wrap around north west. Significant townscape and landscape impacts - exposed site and difficult to integrate remaining non-flood land into townscape. Large part middle of site Flood Zone 3, majority of rest Flood Zone 2. A14 capacity issues. Utility & services require upgrade.
Site 083	Site adjacent to Secondary School to south. Adverse townscape and landscape - dense vegetation / rural & intimate character. Possible smaller scale development. A14 capacity issues. Utility & services require upgrade. 3 landowners.
Site 179	Site to the south east of Market Street. Whole site Flood Zone 3. Significant heritage, townscape and landscape impacts. Noise and odour from scrap yard and sewage pumping station. No highway access. Utility & services require upgrade.
Site 250	Site to north west, adjacent to nationally important SAM. Significant heritage, townscape and landscape impact. Small part Flood Zone 2. Unsuitable highway access - upgrade would be detrimental to rural character. Utility & services require upgrade.
Site 287	Site to the west. Majority Flood Zone 2. Adverse townscape and landscape impact - very exposed site. A14 capacity issues. Utility & services require upgrade.

